

North Main Street Bridge Construction Progress

June 19, 2017

The following work was completed during the weeks of June 5th and June 12th, 2017 by Michael Hansen Construction Ltd.:

- Sealed concrete cracks with silicone joint sealant.
- Chipped out deteriorated concrete from upstream headwall.
- Formed the headwall spalled areas.
- Poured fast-setting mortar in spalled areas.
- Stabilized disturbed slopes with additional seed.



Headwall Repair Areas – Looking Downstream/East



Stabilized Disturbed Slope – Looking North

Final completion of the project is anticipated on June 23rd, 2017.