

Route 97 / Route 28 (Salem Depot) Intersection Improvements Project
Bi-Weekly Progress Report
April 27, 2021

This report identifies the work on the Salem Depot Intersection project that Linskey Excavating, Co. has completed in the last two (2) weeks and is anticipated to be working on during the next two (2) weeks. Roads will remain open, expect delays. Officers will help you pass through the work zones. Thank you for your patience during the construction process.

Work Completed on Salem Depot Intersection

- A large drain manhole was installed adjacent to Salem Cooperative Bank which will accept stormwater from a new catch basin in the east curbline of South Broadway to reduce ponding during large storm events.
- Drainage system work began along the east side of Route 28 to the north of the Salem Depot intersection.



Installation of a large manhole adjacent to Salem Cooperative Bank.



Frame of reference of the size of the drain manhole installed adjacent to Salem Cooperative Bank.



Liberty Utilities holding a utility pole adjacent to the drain pipe excavation to prevent the pole from moving.



Brick and mortar bulkhead of an existing 36" diameter drain pipe to be abandoned.

Next Two (2) Weeks

- Drain pipe and catch basin installation will continue on the east curbline of North Broadway.
- Lighting conduit installation will begin in the vicinity of the intersection.